



Measure Range 0 Degree - 100 Degree Lab Testing Equipment JIS K 7312
ASKER Hard Meter F Type

Technical parameter

Standard	JIS K 7312
Measure range	0degree~100 degree
Minimum scale	1 degree (precision is obtai degree)
Creasing shape (mm) height 2.54	diameter of 5.8 + /-0.2 hemispheres Spring load mN(g)
Spring load mN	(g)
0 degree 539 0	(55±8)
100 degree 8379	(855±8)
Pressure area of about 5.2 mm	(diameter)
Pressure surface (mm) 44 × 18	(rectangular)
Dimension	57×30×76
Weight	200(g)